

FREEMAN 26 FREESPIRIT MAY 2019 OCT 2019

Bilge pump pipe coiled up under floor fit new skin fitting and connect.

Pulpit deck fittings reseal.

Fit immersion heater and one way valve to inlet.

Windscreen wiper not connected and rusty inside replace with two new and wire.

Drain old Petrol from fuel tank.

Refit Navigators seat.

Clean and wash etc the whole in side of the Cabin and Cockpit.

Paint the Cabin roof.

Clean the Cooker.

Hardtop inside Cockpit wash and Paint.

Power wash the Hull and Topsides.

Repaint the Decks sand and apply three coats of Deck paint.

Sand and re varnish the wood lower strakes three coats.

B S inspection , Gas leak indicator faulty , replace oil.

B S inspection Renew fuel pipe to carb.

Survey Fit new washer to Prop.

Survey Free off Stop cock.

Fit and Replace Cabin Sink.

Fit new stop cock Filter.

Strip out Heads Paper walls and renew porta potti after cleaning.

Power wash Hull sand and apply Antifoul.

Wire and fit Shore Power seven sockets , immersion heater.

Wire for TV aerial point to Cabin.

Reseal Cabin roof grab rails.

Compound the Hull and Topsides and Polish.

Repair the Mast and rewire navigation lights.

Refix the Cockpit bench seat back.

Replace Cabin wiring to two ceiling lights.

Replace foam around Windscreen and fit Rope Feature.

Fit new Silent Gliss curtain rail to all Cabin windows.

Clean Anchor and Spray paint.

All external Windows clean off old sealant.

Fit new Mast light socket.

Fit new Horn and socket.

Sort out all wiring to Horn, Search Light and Navigation Lights.

Strip out old Cockpit flooring and renew with Carpet Tiles.

Repair Helm Seat.

Strip out Cabin carpet and Renew.

Relaunch FreeSpirit.

Start Engine and move to Mooring.

Found Water leak under Engine and Bilge pump not working.

Lift out Engine and replace rear core plug and inspect remaining ones.

Run Engine and check.

Carry out test run and found Oil leak on the Gearbox oil cooler return to mooring .

Undo pipe to oil cooler shorten and resolder joint, test all ok.

Rub down Hardtop sides and repaint.

Clean and reproof Cockpit Canopy.

Drill new holes in Guttering on Hardtop to divert water further back.

Remove Cockpit Clock etc sand down and revarnish.

Wire and fit New Automatic Bilge Pump which self tests every 2.5 mins.

Remade Battery terminal on Cockpit clock.

Wash and clean rear Cockpit Seat.

Make and fit all new Cabin Curtains.

Make and fit New External Window Covers to all Cabin Windows.

Make and fit Cockpit Step.

New Chrome Fender Cleats fitted to Port and Starboard Decks.

New Mooring ropes fitted (four)

New Fenders fitted all round including Two Bulbs and a Bow Fender.

New Name Signs Fitted to Hull and Stern.

Refit the Solar Panel Control box in the Cockpit.

Remove front Window Eye Brows clean and apply new mastic and refit.

Replace all Chrome Grab Rail end Caps x 8.

Wire and fit 180 watt Tubular Heater to the Engine Bay.

Replace all Cabin Cushions and Foam (Jeckells Wroxham)